


Precision temperature sensors for SWAN transmitters.  
The sensor type used depends on the transmitter model.

**Swansensor NT5K**  
**Swansensor Pt1000**

**Specifications**

Sample temperature: up to 100 °C  
Sample pressure: up to 10 bar at 25 °C  
up to 5 bar at ≥ 80 °C  
Material: stainless steel 1.4435, SS 316L  
Connection: PG13.5, screw plug  
Protection degree: IP 68



Swansensor NT5K / Pt1000

Order scheme	Swansensor Temperature	A-87.0	X	0.200
Sensor	<b>Swansensor NT5K</b> precision temperature sensor.....		2	
	<b>Swansensor Pt 1000</b> precision temperature sensor .....		3	

Order scheme	Cables for above temperature sensors	A-88.131.	X	20
Sensor cable	Sensor cable (sleeves/screw plug), 1 m .....		1	
	Sensor cable (sleeves/screw plug), 5 m .....		5	
	Sensor cable (sleeves/screw plug), 10 m .....		6	
	Sensor cable (sleeves/screw plug), 15 m .....		7	